GLASSBORO PUBLIC SCHOOLS

DISTRICT PROJECT UPDATE

November 2026

District Wide Projects

High School

Description	Actions	Status
New roof leak	• Band aid	Work in progress
DEP of New Jersey Violation Year 2009	• Architect FVHD	Work in progress
During annual inspection of Fire Alarm Panel some deficiencies were found	• Parts were ordered • Encore Fire Protection LLC	Completed
CST HVAC unit bad motor	• Ordered • In-house	Completed

Bowe

Description	Action	Status
Gym Roof replacement	• Referendum	Work in progress
Gym Painting	• Referendum	Work in progress
Gym new Wood floor	• Referendum	Work in Progress
Gym new Bleachers	• Referendum	Work in progress
Gym wall padding	• Referendum	Work in progress
Gym Scoreboard	• Referendum	Work in progress
During annual inspection of Fire Alarm Panel some deficiencies were found	• Parts were ordered • Encore Fire Protection LLC	Completed
Girls restroom exhaust fan bad	• Getting price	Open
Kitchen Hot water expansion tank leaking	• Ordered part • In-house	Completed

Bullock

Description	Actions	Status
During annual inspection of Fire Alarm Panel some deficiencies were found	• Parts were ordered • Encore Fire Protection LLC	
Media Center HVAC motor good but bearing is bad	• Parts were ordered • In-House	Completed
Cafeteria exhaust fan bad bearings	• Parts were ordered • In-House	Open
Leak outside School main office	• Northeast mechanical	Open

Rodgers

Description	Actions	Status
Cafeteria Unit 1 needs new compressor	• Waiting for quote	Open
Cafeteria Unit 2 needs to be replaced	• Waiting for quote	Open
Boiler #2 Heat exchanger(vessel) is leaking	• Just receive a quote	Open
School Office copier room roof leak, Hallways	• Summer Work (Referendum)	Work in progress
New roof (Replacement)	• Referendum	Work in progress
Hallway outside Boiler room roof leak	• Summer Work (Referendum)	Work in progress
During annual inspection of Fire Alarm Panel some deficiencies were found	• Parts were ordered • Encore Fire Protection LLC	Completed
Hot water heater bad m**otor and impeller**	• Parts were ordered • In-house	Completed
Lochinvar boiler #**2** during annual inspection the fan assembly needed to be replaced	• Parts were ordered • Northeast Mechanical	Open
Classroom A3 Broken heating coil	• Isolate the valve • Waiting for estimates	Open
Classroom D6 broken h**eating** coil	• Isolate the valve • Waiting for estimate	Open
Classroom D3 Complains air quality	• Caled EDI to take samples of the air in the classroom	Completed
Exhaust fan is bad	• Getting price	Open

Beach

Description	Action	Status
New Roof (Replacement)	• Referendum	Work in progress
	•	

Ops/Transportation

Description	Action	Status
	•	

Mitcho ECC

Description	Action	Status
	•	

District Wide

Description	Status
•	