

GLASSBORO PUBLIC SCHOOLS

DISTRICT PROJECT UPDATE

SEPTEMBER 2024

District Wide Projects

High School

Description	Actions	Status
Culinary room Three sink compartment needs to be installed, also a grease trap.	<ul style="list-style-type: none">FVHD Architects	Open
Trane RTU one compressor is bad	<ul style="list-style-type: none">Getting quotes to replace compressor	Open
Leaks in guidance are by copier and conference room due to last storm and high winds	<ul style="list-style-type: none">Work will be done in-house	Completed
2024 Annual fire extinguisher inspection	<ul style="list-style-type: none">Ankor	Completed
2024 annual sprinklers system	<ul style="list-style-type: none">ABJ'S	Complete
ABJ'S Sprinkler during the annual inspection found some deficiency in the sprinkler system	<ul style="list-style-type: none">Waiting for quote	Open
2024 annual Fire alarm inspection	<ul style="list-style-type: none">Franklyn Alarm	Completed
Due to the rename of the classrooms, the fire alarm system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none">Franklyn Alarm	Open
Due to the rename of the classrooms, the BAS system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none">Waiting for a quote from Bradly-Sciocchetti Inc	Open
New roof leak by room B12 near door.	<ul style="list-style-type: none">	Open

Bowe

Description	Action	Status
Several leaks in usual places, due to heavy rains	<ul style="list-style-type: none">• Work will be done in-house	Work in progress
Classrooms C123 & C137 VCT Tiles need to be replace	<ul style="list-style-type: none">• A&J Flooring	Completed
Replace 7 season 4 RTU's	<ul style="list-style-type: none">• All Coast	Work in progress
Washer and Dry was installed in the weight room	<ul style="list-style-type: none">• Northeast Plumbing	Completed
2024 annual fire extinguisher inspection	<ul style="list-style-type: none">• Ankor	Completed
2024 Annual fire sprinklers system	<ul style="list-style-type: none">• ABJ'S	Completed
ABJ'S Sprinkler during the annual inspection found some deficiency in the sprinkler system	<ul style="list-style-type: none">• Waiting for a quote	Open
2024 Annual Fire Alarm Inspection	<ul style="list-style-type: none">• Franklyn Alarm	Completed
Due to the rename of the classrooms, the fire alarm system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none">• Franklyn Alarm	Open
Parking lines need to be repainted	<ul style="list-style-type: none">• Work will be done in-house	Work in progress
Due to the rename of the classrooms, the BAS system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none">• Waiting for a quote from Bradly-Sciocchetti Inc	Open

Bullock

Description	Actions	Status
Parking Lines need to be-repaint	<ul style="list-style-type: none">• In-house grounds and maintenance teams	Work in progress
Wheelchair ramp in the back of the school needs to be repaired.	<ul style="list-style-type: none">• Waiting for quotes	Open
2024 Annual fire extinguisher inspection	<ul style="list-style-type: none">• Ankor	Work in progress
2024 annual sprinklers system	<ul style="list-style-type: none">• ABJ'S	Work in progress
ABJ'S Sprinkler during the annual inspection found some deficiency in the sprinkler system	<ul style="list-style-type: none">• Waiting for a quote	Open
2024 annual Fire alarm inspection	<ul style="list-style-type: none">• Franklyn Alarm	Completed
Due to the rename of the classrooms, the fire alarm system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none">• Franklyn Alarm	Open
Due to the rename of the classrooms, the BAS system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none">• Waiting for a quote from Bradly-Sciocchetti Inc	Open

Rodgers

Description	Actions	Status
Parking lanes need to be repainted	<ul style="list-style-type: none"> • Grounds and maintenance team 	Open
WJ Gross look at the overhang by the pole	<ul style="list-style-type: none"> • WJ Gross put up support to the overhang. 	Work in progress
Gym floor will be replaced	<ul style="list-style-type: none"> • Contractor 	Work in progress
Cafeteria Unit 3 Ventilator coil broke needs to be replace.	<ul style="list-style-type: none"> • Northeast Mechanical 	Open
Cafeteria Unit 1 needs new compressor	<ul style="list-style-type: none"> • Northeast Mechanical 	Open
New Playground was installed	<ul style="list-style-type: none"> • 	Work in progress
2024 Annual fire extinguisher inspection	<ul style="list-style-type: none"> • Ankor 	Completed
2024 annual sprinklers system	<ul style="list-style-type: none"> • ABJ'S 	Completed
2024 annual Fire alarm inspection	<ul style="list-style-type: none"> • Franklyn Alarm 	Completed
Due to the rename of the classrooms, the fire alarm system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none"> • Franklyn Alarm 	Open
Due to the rename of the classrooms, the BAS system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none"> • Waiting for a quote from Bradly-Sciocchetti Inc 	Open
August 24, we had an HVAC issue in the faculty bathroom B-14 the ceiling unit heating coil broke, we had a flood in the school. No major damage.	<ul style="list-style-type: none"> • Northeast Mechanical waiting for a quote 	Open

Beach

Description	Action	Status
	•	

Ops/Transportation

Description	Action	Status
Recommended purchasing more cameras for the far end of the bus yard and maintenance garage for better coverage.	•	Work in progress

District Wide

Description	Status
<ul style="list-style-type: none"> • I want to thank my entire team for their hard work during the summer to have the facilities ready for school. 	Information only
<ul style="list-style-type: none"> • Total Work orders 1887, Open 30 as of 9/5/2024 	Information only