

# GLASSBORO PUBLIC SCHOOLS

## DISTRICT PROJECT UPDATE

SEPTEMBER 2024

District Wide Projects

### High School

<b>Description</b>	<b>Actions</b>	<b>Status</b>
Culinary room Three sink compartment needs to be installed, also a grease trap.	<ul style="list-style-type: none"><li>• FVHD Architects</li></ul>	Open
Trane RTU one compressor is bad	<ul style="list-style-type: none"><li>• Getting quotes to replace compressor</li></ul>	Open
LEAD Water Testing	<ul style="list-style-type: none"><li>• EDI</li></ul>	Work in Progress
Main hallway water leak	<ul style="list-style-type: none"><li>• Northeast plumbing</li></ul>	Open
ABJ'S Sprinkler during the annual inspection found some deficiency in the sprinkler system	<ul style="list-style-type: none"><li>• Waiting for quote</li></ul>	Open
Due to the rename of the classrooms, the fire alarm system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none"><li>• Franklyn Alarm</li></ul>	Work in Progress
Due to the rename of the classrooms, the BAS system needs to be reprogram with the new classroom number.	<ul style="list-style-type: none"><li>• Waiting for a quote from Bradly-Sciocchetti Inc</li></ul>	Open
New roof leak by room B12 near door.	<ul style="list-style-type: none"><li>•</li></ul>	Open

**Bowe**

<b>Description</b>	<b>Action</b>	<b>Status</b>
Several leaks in usual places, due to heavy rains	<ul style="list-style-type: none"><li>• Work will be done in-house</li></ul>	Work in progress
Replace 7 season 4 RTU's	<ul style="list-style-type: none"><li>• All Coast</li></ul>	Work in progress
Fire alarm went off in the building	<ul style="list-style-type: none"><li>• FFD Responded</li><li>• Building evacuated</li></ul>	Information Only
LEAD Water testing	<ul style="list-style-type: none"><li>• EDI</li></ul>	Work in Progress
ABJ'S Sprinkler during the annual inspection found some deficiency in the sprinkler system	<ul style="list-style-type: none"><li>• Waiting for a quote</li></ul>	Open
Due to the rename of the classrooms, the fire alarm system needs to be reprogram with the new classroom number.	<ul style="list-style-type: none"><li>• Franklyn Alarm</li></ul>	Work in Progress
Parking lines need to be repainted	<ul style="list-style-type: none"><li>• Work will be done in-house</li></ul>	<i>Completed</i>
Due to the rename of the classrooms, the BAS system needs to be reprogram with the new classroom number.	<ul style="list-style-type: none"><li>• Waiting for a quote from Bradley-Sciocchetti Inc</li></ul>	Open

**Bullock**

<b>Description</b>	<b>Actions</b>	<b>Status</b>
Parking Lines need to be-repaint	<ul style="list-style-type: none"><li>• In-house grounds and maintenance teams</li></ul>	Work in progress
Wheelchair ramp in the back of the school needs to be repaired.	<ul style="list-style-type: none"><li>• Waiting for quotes</li></ul>	Open
LEAD Water Testing	<ul style="list-style-type: none"><li>• EDI</li></ul>	Work in progress
2024 annual sprinklers system	<ul style="list-style-type: none"><li>• ABJ'S</li></ul>	Completed
ABJ'S Sprinkler during the annual inspection found some deficiency in the sprinkler system	<ul style="list-style-type: none"><li>• Waiting for a quote</li></ul>	Open
Due to the rename of the classrooms, the fire alarm system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none"><li>• Franklyn Alarm</li></ul>	Work in Progress
Due to the rename of the classrooms, the BAS system needs to be reprogram with the new classroom number.	<ul style="list-style-type: none"><li>• Waiting for a quote from Bradly-Sciocchetti Inc</li></ul>	Open

**Rodgers**

<b>Description</b>	<b>Actions</b>	<b>Status</b>
Parking lanes need to be repainted	<ul style="list-style-type: none"><li>• Grounds and maintenance team</li></ul>	Open
WJ Gross look at the overhang by the pole	<ul style="list-style-type: none"><li>• WJ Gross put up support to the overhang.</li></ul>	Work in progress
Gym floor will be replaced	<ul style="list-style-type: none"><li>• Contractor</li></ul>	Work in progress
Cafeteria Unit 3 Ventilator coil broke needs to be replace.	<ul style="list-style-type: none"><li>• Northeast Mechanical</li></ul>	Open
Cafeteria Unit 1 needs new compressor	<ul style="list-style-type: none"><li>• Northeast Mechanical</li></ul>	Open
New Playground was installed	<ul style="list-style-type: none"><li>•</li></ul>	Work in progress
LEAD Water testing	<ul style="list-style-type: none"><li>• EDI</li></ul>	Work in progress
Main School Office Unit needs a new compressor.	<ul style="list-style-type: none"><li>• Northeast Mechanical</li></ul>	Open
Due to the rename of the classrooms, the fire alarm system needs to be reprogramed with the new classroom number.	<ul style="list-style-type: none"><li>• Franklyn Alarm</li></ul>	Work in Progress
Due to the rename of the classrooms, the BAS system needs to be reprogrammed with the new classroom number.	<ul style="list-style-type: none"><li>• Waiting for a quote from Bradly-Sciocchetti Inc</li></ul>	Open
August 24 we had an HVAC issue in the faculty bathroom B-14 the ceiling unit heating coil broke, we had a flood in the school. No major damage.	<ul style="list-style-type: none"><li>• Northeast Mechanical waiting for a quote</li></ul>	Open

**Beach**

Description	Action	Status
LEAD Water testing	<ul style="list-style-type: none"> <li>• EDI</li> </ul>	Work in Progress

**Ops/Transportation**

Description	Action	Status
Recommended purchasing more cameras for the far end of the bus yard and maintenance garage for better coverage.	<ul style="list-style-type: none"> <li>•</li> </ul>	Work in progress
LEAD Water Testing	<ul style="list-style-type: none"> <li>• EDI</li> </ul>	Work in Progress

**District Wide**

Description	Status
<ul style="list-style-type: none"> <li>• Total Work orders 2017, Open 40 as of 10/9/2024</li> </ul>	Information only