# GLASSBORO PUBLIC SCHOOLS DISTRICT PROJECT UPDATE

June 2025

## **District Wide Projects**

## High School

Description	Actions	Status
Culinary room Three sink compartments	<ul> <li>FVHD Architects</li> </ul>	Work is
need to be installed, also a grease trap.		expected to
		begin in late
		June
Trane RTU one compressor is bad	<ul> <li>Getting quotes to</li> </ul>	Open
	replace compressor	
Football Stadium. Four sprinkler heads	Work will be done in	Work in
need to be replaced,	house	progress

#### **Bowe**

Description	Action	Status
Boys Locker room new roof leak	<ul> <li>Work will be done in</li> </ul>	Work in
	house	progress
Replace 7 season 4 RTU's	All Coast	Work in
We are still experiencing issues with the		progress
new 7 units, and contractors are actively		
working to resolve the problems.		
The frame of Door #2 in the top left-hand	Make a temporary repair	Open
corner is broken.	and getting estimates.	
New LED Light fixtures are being installed in	Work is done in house	Work in
the entire School about (975 light fixtures)		progress

### Bullock

Description	Actions	Status
December 30, 2024, we lost a heating	<ul> <li>Northeast Mechanical</li> </ul>	Work in
pump, and the pump was still running but	<ul> <li>Six coils has been</li> </ul>	progress
the pump seal went and causing lock of	replaced.	
flow to one wing due to the stream	<ul> <li>An additional four coils</li> </ul>	
weather 11 frozen coils. Units are 30 years	will be replaced once	
old. Recommendation replace the eleven	school is out	
units.		

Wheelchair ramp in the back of the school	<ul> <li>Waiting for quotes</li> </ul>	Open
needs to be repaired.		
On January 23, 2025, both boilers went down, and we lost another coil in room	<ul> <li>Northeast Mehanical boilers are ok.</li> </ul>	Completed
B36. We were able to get one boiler	Waiting for a Quote to	Open
running, but had to call for service for the second one. The technician found a faulty	replace coil.	
electrolyte.		

## Rodgers

Description	Actions	Status
Cafeteria Unit 1 needs new compressor	<ul> <li>Waiting for quote</li> </ul>	Open
Cafeteria Unit 2 needs to be replaced	<ul> <li>Waiting for quote</li> </ul>	Open
Cafeteria unit 3 has a freon leak	Repaired will be done in house	Work in progress
On November 20, a second broken coil was discovered in room A15. Fortunately, there was no water damage due to the quick response of our housekeeper. We attempted to repair the coil in place, but there were too many holes, making it beyond repair.	<ul> <li>John Verderama &amp; Sons, Inc</li> <li>Coil has been ordered 6 to 8 weeks lead time</li> </ul>	Work in Progress
On December 11, 2024 another broken coil room A13	<ul> <li>John Verderama &amp; Son Inc.</li> <li>Coil has been order 6 to 8 weeks lead time</li> </ul>	Work in progress
IT Closet HVAC broken.	<ul><li>John Verderama &amp; Son Inc.</li><li>ordered</li></ul>	Work in progress

#### Beach

Description	Action	Status
IT Server Room. Needs a backup HVAC unit .	<ul> <li>Work will done in</li> </ul>	Ordered
looking for the best option	house	

### **Ops/Transportation**

Description	Action	Status
Recommended purchasing more cameras for	•	open
the far end of the bus yard and maintenance		
garage for better coverage.		

#### **District Wide**

Description	Status
Due to the ongoing inclement weather and heavy rainfall on Friday May	Some of these
16, 2025 , we experience several leaks across the district. The affected	leaks have
areas include:	been
	addressed
<ul> <li>Rodgers School: New leak near the copier room in the main office</li> </ul>	internally.
<ul> <li>Bullock School: Room B53 (new leak) and the hallway near the nurse's office (new)</li> </ul>	
Bowe School: C Hallway and the area near the courtyard by	
Classroom D21	
GHS: A few leaks throughout the building	
•	
<ul> <li>Total Work orders 2503, Open 30 as of6/6/2025</li> </ul>	Information only