

GLASSBORO PUBLIC SCHOOLS

DISTRICT PROJECT UPDATE

August 2025

District Wide Projects

High School

Description	Actions	Status
Culinary room Three sink compartments need to be installed, also a grease trap.	<ul style="list-style-type: none">FVHD Architects	Work in progress
Trane RTU one compressor is bad	<ul style="list-style-type: none">Getting quotes to replace compressor	Open
Football Stadium. New Scoreboard was installed.	<ul style="list-style-type: none">Vendor	Completed
Runing a new electrical outlet 120V for the new scoreboard at the football stadium.	<ul style="list-style-type: none">In-house	Work in progress
New IT Classroom Adding more electrical outlets.	<ul style="list-style-type: none">Will be done in house	Work in progress

Bowe

Description	Action	Status
Boys Locker room new roof leak	<ul style="list-style-type: none">Work will be done in house	Completed
Replace 7 season 4 RTU's We are still experiencing issues with the new 7 units, and contractors are actively working to resolve the problems.	<ul style="list-style-type: none">All Coast	Work in progress
The frame of Door #2 in the top left-hand corner is broken.	<ul style="list-style-type: none">Make a temporary repair and getting estimates.	Open
New LED Light fixtures are being installed in the entire School about (975 light fixtures)	<ul style="list-style-type: none">All classrooms, hallways and office light fixture are completed.Working on the outside lights	Completed

Bullock

Description	Actions	Status
December 30, 2024, we lost a heating pump, and the pump was still running but	<ul style="list-style-type: none">Northeast Mechanical	Work in progress

the pump seal went and causing lock of flow to one wing due to the stream weather 11 frozen coils. Units are 30 years old. Recommendation replace the eleven units.	<ul style="list-style-type: none"> • Six coils has been replaced. • An additional four coils will be replaced once school is out 	
Wheelchair ramp in the back of the school needs to be repaired.	<ul style="list-style-type: none"> • Waiting for quotes 	Open
On January 23, 2025, both boilers went down, and we lost another coil in room B36. We were able to get one boiler running, but had to call for service for the second one. The technician found a faulty electrolyte.	<ul style="list-style-type: none"> • Northeast Mechanical boilers are ok. • Waiting for a Quote to replace coil. 	Completed Open

Rodgers

Description	Actions	Status
Cafeteria Unit 1 needs new compressor	<ul style="list-style-type: none"> • Waiting for quote 	Open
Cafeteria Unit 2 needs to be replaced	<ul style="list-style-type: none"> • Waiting for quote 	Open
	<ul style="list-style-type: none"> • 	
On November 20, a second broken coil was discovered in room A15. Fortunately, there was no water damage due to the quick response of our housekeeper. We attempted to repair the coil in place, but there were too many holes, making it beyond repair.	<ul style="list-style-type: none"> • John Verderama & Sons, Inc • Coil has been ordered 6 to 8 weeks lead time 	Work in Progress
On December 11, 2024 another broken coil room A13	<ul style="list-style-type: none"> • John Verderama & Son Inc. • Coil has been order 6 to 8 weeks lead time 	Work in progress
IT Closet HVAC broken.	<ul style="list-style-type: none"> • Repaired will be done in house 	Work in progress

Beach

Description	Action	Status
New LED Light fixtures are being installed in the entire Beach Building	<ul style="list-style-type: none">• Work will done in house	Work in progress

Ops/Transportation

Description	Action	Status
Recommended purchasing more cameras for the far end of the bus yard and maintenance garage for better coverage.	<ul style="list-style-type: none">• Cat6 cable was run in house .	Work in progress

District Wide

Description	Status
<ul style="list-style-type: none">• Total Work orders 2580, Open 20 as of 7/14/2025	Information only