# GLASSBORO PUBLIC SCHOOLS DISTRICT PROJECT UPDATE

## October 2025

## **District Wide Projects**

# High School

Description	Actions	Status
New roof leak	<ul><li>In house</li></ul>	Work in
		progress
Couple door closer replace	<ul> <li>JC Magee Locksmith</li> </ul>	In progress

#### **Bowe**

Description	Action	Status
Replace 7 season 4 RTU's	All Coast	Completed.
We are still experiencing issues with the		
new 7 units, and contractors are actively		
working to resolve the problems.		
The frame of Door #2 in the top left-hand	In house.	Completed
corner is broken.		
Couple door closer replace	<ul> <li>JC Magee Locksmith</li> </ul>	In progress

#### **Bullock**

Description	Actions	Status
December 30, 2024, we lost a heating	<ul> <li>Northeast Mechanical</li> </ul>	Work in
pump, and the pump was still running but	<ul> <li>Six coils has been</li> </ul>	progress
the pump seal went and causing lock of	replaced.	
flow to one wing due to the stream	<ul> <li>An additional four coils</li> </ul>	
weather 11 frozen coils. Units are 30 years	will be replaced once	
old. Recommendation replace the eleven	school is out	
units.		
Wheelchair ramp in the back of the school	<ul> <li>Waiting for quotes</li> </ul>	Open
needs to be repaired.		
On January 23, 2025, both boilers went	<ul> <li>Northeast Mechanical</li> </ul>	Completed
down, and we lost another coil in room	boilers are ok.	
B36. We were able to get one boiler	<ul> <li>Waiting for a Quote to</li> </ul>	Open
running, but had to call for service for the	replace coil.	
second one. The technician found a faulty		
electrolyte.		

Playground Area 60 yards of mulch	<ul> <li>In house Grounds team</li> </ul>	Work in
		progress
Couple door closer replace	<ul> <li>JC Magee Locksmith</li> </ul>	In progress

# Rodgers

Description	Actions	Status
Cafeteria Unit 1 needs new compressor	<ul> <li>Waiting for quote</li> </ul>	Open
Cafeteria Unit 2 needs to be replaced	<ul> <li>Waiting for quote</li> </ul>	Open
Couple door closer replace	JC Magee Locksmith	In progress
On November 20, a second broken coil was discovered in room A15. Fortunately, there was no water damage due to the quick response of our housekeeper. We attempted to repair the coil in place, but there were too many holes, making it beyond repair.	<ul> <li>John Verderama &amp; Sons, Inc</li> <li>Coil has been ordered 6 to 8 weeks lead time</li> </ul>	Work in Progress
On December 11, 2024 another broken coil room A13	<ul> <li>John Verderama &amp; Son Inc.</li> <li>Coil has been order 6 to 8 weeks lead time</li> </ul>	Work in progress
Couple door closer replace	JC Magee Locksmith	In progress

## Beach

Description	Action	Status
New LED Light fixtures are being installed in	<ul> <li>Work will done in</li> </ul>	Work in
the entire Beach Building	house	progress

# Ops/Transportation

Description	Action	Status
New LED Light fixtures are being installed in	Work will done in house	Work in
the entire OPS Office and Grounds Shop		progress
Recommended purchasing more cameras for	<ul> <li>Cat6 cable was run in</li> </ul>	Work in
the far end of the bus yard and maintenance	house .	progress
garage for better coverage.		

#### **District Wide**

Description	Status
<ul> <li>Total Work orders 2745, Open10 as of 10/5/2025</li> </ul>	Information only