

Health and Safety Evaluation Of School	Buildi	ngs C	heck	list 2021-2022
County: GLOUCESTER District Occup	ying Bu	ilding	: GLA	ASSBORO
(check one) Leased Owned School Building Na	me: GL	ASSB	ORO I	INTERMEDIATE
Completed By: LaVonya Mitchell, Richard Booth			Da	ate: 1/10/2022
This form shall be used for the evaluation of school buildings (Public School Districts (owned or leased), Private Schools for the School Projects and any other setting used for instruction. This annually by appropriate district personnel and kept on file for cover regulations issued by NJDOE, NJDCA, NJUCC, OSHA. The stafety of students and staff even in the absence of a specific Sexclusive of other findings a monitor/inspector may site. See additional information. Section A: 100% Items this section must have full compliance with items) 100% Compliance	he Disabl s evaluati inspectic emphasi tatute or	ed, Ch ion che on or o s of th Code.	arter S ecklist s ther le _l is evalu The ite	chools, Renaissance shall be completed gal issues. These indicators uation is for the health and
Current Licenses and Certificates #1 to #10	Yes	No	N/A	Violation Location
 A current certificate of compliance with the Uniform Fire Code has been issued by the local or State fire official/inspector within the year and posted in a conspicuous location. (or current abatement inspection is available) 	V			
2. A current inspection report of the local health official (kitchen, cafeteria, pool, etc.) is available.	V			
3. A 3 year asbestos management plan, as required by A.H.E.R.A., is available including current 6 month surveillance letters. If constructed without asbestos, a letter of certification from the				

architect is available.

4. An annual inspection report of the Department of

treatment plant, where applicable, is available.

as required by code, are properly posted.

Lead Testing Statement of Assurance.

Environmental Protection for the operation of a sewage

5. Current boiler inspection certificate(s) posted at site of boiler. **6.** Current license(s) for high and low pressure boiler operators,

7. Current drinking water supply inspection reports are available to comply with the Safe Water Drinking Act. (N.J.A.C 58:12A-1) (6A:26-12.4)Also, evidence of testing of water for lead has been provided by the district through annual submittal of the

Interior #13 to #21	Yes	No	N/A	Violation Location
20. Dangerous chemicals (i.e., liquefied petroleum gas/propane) and/or explosive materials (i.e.: gunpowder; picric acid) are not stored/present in the building. If needed, flammable and combustible materials are properly stored/maintained (i.e., in properly rated cabinets; not in boiler room/hazardous areas).				
 21. Carbon Monoxide Detectors (new) Must be in the vicinity of all fuel burning appliances. Gas and oil heating systems: Boilers, Furnaces, central and unitary equipment. Generators: portable and permanent. Natural gas and propane appliances: Water heaters, ranges, stoves, ovens, laundry washers and dryers Fireplaces Required in hallways connected to space with the source NJAC 5:70-4.3(a), NJAC 5:70-4.9(d) and NJAC 5:70-4.19 (d) 	√			
Vocational/Laboratories #22 to #25	Yes	No	N/A	Violation Location
 22. Power machinery and equipment, as well as science labs, have appropriate safety features in place, including as applicable: a. Appropriate placement on the floor and required point of operation guards to protect users from injury due to moving parts. b. Clearly visible and accessible push-type emergency cut-out switches at appropriate locations within shops to deenergize electrical supply to nonportable machinery. c. Non-portable machinery provided with magnetic type switches to prevent automatic restart upon restoration of power after an electrical failure or reactivation of the emergency cut-off switch. d. Key-operated electric solenoid shut-off valves on natural gas lines in science laboratories and shops constructed after 1979. On all other gas lines there is an emergency shut off valve which is clearly marked and accessible. 23. At a minimum, one # 20 BC rated fire extinguisher is provided 	√			
in each laboratory and vocational area.	V			
 24. Adequate eye and body protection is provided, including: a. Eye protection devices (glasses, goggles) for students and faculty in each laboratory and shop area, including appropriate provision for their sanitation. b. Emergency eyewash device(s), with 15 minutes continuous flow, where caustic or corrosive materials are used. c. An emergency cold-water shower for chemistry laboratory if constructed after October 1985. (NJAC 6A:26-12.5) 	<u></u> ✓			

Section B: 80% Items

(Must be compliant with 80% of these items to pass along with corrective action on the non compliant items) 80% Compliance

Folk /File is the same		pate in	1111	
Exits/Exterior #1 to #4 1. No evidence of major exterior building structural damage.	Yes	No	N/A	Violation Location
 Example(s) would include: a. Exterior walls appear free of structural cracks, loose masonry and crumbling parapets; lintels appear free of rust and flaking. b. Gutters and downspouts appear to be in good condition and are secured to the building; runoff does not appear to be obstructed or create drainage or soil erosion. 	✓			
2. All exterior receptacles are GFI protected in accordance with code.	V			
athletic fields, are free of holes; glass; stumps, roots; rocks and other hazardous obstacles. Fences are maintained and are free of holes. The outside physical education area for students shall include, but not be limited to, sufficient space, equipment, and safe surfaces for the temporary facility enrollment and program needs and be protected from hazards or traffic conditions. 6A:26-8.1ix	✓			
4. Playground area and equipment appear to be in safe operating condition and in compliance with code and district maintains documentation of compliance and regular (annual and/or monthly) inspections.			√	
Interior Items #5 to #26	Yes	No	N/A	Violation Location
All interior exits and corridors are in good condition; readily accessible; and free of obstructions and/or excessive materials which would hinder exiting.	V			
6. Emergency evacuation egress procedures are posted at a visible height and standard location in all areas. 6A:26-8.1 (i4)	V			
 Doors leading to interior courtyards are clearly marked: "Not an Exit." 	V			1
B. Handrails on both sides of interior stairways, guardrails, and interior stair treads are free of surface features which may cause injury and/or are properly secured. Interior stair treads do not show evidence of extensive wear and are generally in good repair.	✓			
Stage curtains need to indicate flame proof or flame retardant and certificates are on file.			V	Harris Harris
10. All education spaces shall be equipped with a communication devise/system connected to the main office and capable of emergency communication to local authorities or 9-1-1. 6A:26-8.1 (i6).	✓			

Interior Items #5 to #26	TV	Ma	31/4	The first section of the section of
21. Provision shall be made for storage of students' clothing in other than a corridor or exitway. Student lockers are usable; i.e.; doors, handles and locks are operable. 6A:26-8.1 (i7)	Yes	No	N/A	Violation Location
22. Drinking fountains are provided with sufficient water pressure or access to water coolers is readily available. (6A:26-12.4) Potable water shall be available and drinking fountains shall be provided for students in cafeterias, preschool and kindergarten programs in accordance with N.J.A.C. 5:23-7; 6A:26-8.1(v).	V			
23. Toilet facilities shall meet existing UCC requirements for the E Use Group as determined by the construction official. Toilet facilities shall be available within a reasonable distance not more than one floor away, and shall be equipped with an exterior operable window sash or mechanical exhaust ventilation. 6A:26-8.1 (iv)	√			
24. Food and nonfood items (i.e.: cleaning products, etc.) in home economics rooms & cafeteria are stored separately.	\checkmark			
25. Non-instructional areas are free of all unapproved construction; e.g.: walls, partitions, doors and stairs.	V			
26. Furniture and equipment that is in good condition and suitable for the age and size of the students and purposes of instruction shall be provided; NJAC 6A:26-8.1(vii)	✓			
Vocational/Laboratories #27 to #34	Yes	No	N/A	Violation Location
27. Corrosives, toxic and other hazardous substances are stored in proper corrosive storage cabinets and are properly labeled.	V			VIOLATION ECCATION
28. Required space is available for the safe operation of machinery.	V			
29. Mechanical and hydraulic automotive lifts have locking devices to hold them in the extended (open) position.			V	
30. Floor(s) and aisles in all shops are free of slipping and tripping hazards.	✓			
31. "Eye Hazard Area- Wear Your Eye Protection" signs are posted.				
 32. The following additional safety measures are in place if welding operations are on-going: a. Welding curtains are provided and are painted with a finish of low reflectivity. b. Personal protective equipment (goggles, aprons, etc.) are provided. 			√	
 welding operations are on-going: a. Welding curtains are provided and are painted with a finish of low reflectivity. b. Personal protective equipment (goggles, aprons, etc.) are 			✓	

Facility Score 2021-2022

		ring Sections	100% Section A	80% Section B			
Maximum # of Compliant Questions: 25			25	34			
100% Section A Compliance	Score	NJQSAC FISCAL	. DPR [All items are in co	mpliance in building(s)]			
# of No responses in section A	0	\$190000000	nnt (No Exceptions) mpliant (Corrective Actio	on Needed)			
80% Section B Compliance	Score	NJQSAC DPR [At least 80% of	items are in compliance	in building(s))			
A. Number of Yes responses	28			an sanding(s/)			
B. Number of No responses	1	Compliant Line (A) is equal to or greater than Line (D)					
C. Subtotal [A + B]	29						
D. Multiply [(C) × 80%]	23.2	Non-Compliant Line (A) is less than Line (D)					
	LEA AS	ssurance Sign	atures				
School Facility Name <u> </u>	C 2	Intermediar					
Lavoryra Mitchall	<u>Q</u> (Rincipa	Q	1-12-2022 Date			
123			1110/2022	Date			
f applicable, Certified Educational Fac	cilities Manger	Da					
hief School Administrator		Da	te				