

GLASSBORO PUBLIC SCHOOLS

DISTRICT PROJECT UPDATE

JUNE 2024

District Wide Projects

High School

Description	Actions	Status
Culinary room Three sink compartment needs to be installed, also a grease trap.	<ul style="list-style-type: none">• FVHD Architects	Open
High School cooling tower. Two strainers need to be replaced	<ul style="list-style-type: none">• Northeast Mechanical	Open
Leaks in guidance are by copier and conference room due to last storm and high winds	<ul style="list-style-type: none">• Work will be done in-house	Open
Fire alarm went off in the building	<ul style="list-style-type: none">• FD Responded.• Building evacuated	Information Only
Trane Chiller went down, control issues	<ul style="list-style-type: none">• Called Northeast Mechanical and Bradley Siochetti	Work in progress

Bowe

Description	Action	Status
Several leaks in usual places, due to heavy rains	<ul style="list-style-type: none">• Work will be done in-house	Work in progress
Classrooms C123 & C137 VCT Tiles need to be replace	<ul style="list-style-type: none">• Looking for quotes	Open

Bullock

Description	Actions	Status
NJ Elevator Department Notice of Violation. The handicap lift by the Gym not working properly. 90 days grace period.	<ul style="list-style-type: none"> Contact our vendor Metro Elevator Inc. 	completed
Roof leak in classroom C-36 due to heavy rain	<ul style="list-style-type: none"> Work will be done in-house 	Open
Art-room and D9 need a new motor	<ul style="list-style-type: none"> Motor was ordered 	Completed
Wheelchair ramp in the back of the school needs to be repaired.	<ul style="list-style-type: none"> Work will be done in-house 	Open

Rogers

Description	Actions	Status
The following classrooms have a bad freeze stat and fan cycle control : A1-A10	<ul style="list-style-type: none"> Northeast Mechanical 	Work in progress
Housekeeper Kendrick Huston, Mr Huston is replacing Kimberly Bullock	<ul style="list-style-type: none"> Waiting for board approval 	Completed
WJ Gross look at the overhang by the pole	<ul style="list-style-type: none"> WJ Gross put up support to the overhang. 	Work in progress
<ul style="list-style-type: none"> Gym floor will be replaced 	<ul style="list-style-type: none"> Contractor 	Open

Beach

Description	Action	Status
Leak by HR's office from recent rain.	<ul style="list-style-type: none"> Work will be done in-house. 	Work in progress

Ops/Transportation

Description	Action	Status
<ul style="list-style-type: none"> Recommended purchasing more cameras for the far end of the bus yard and maintenance garage for better coverage. 	<ul style="list-style-type: none"> 	Open

District Wide

Description	Status
<ul style="list-style-type: none">• We had our annual fire inspection throughout the district, fire inspector found 6 deficiencies.	Information only
<ul style="list-style-type: none">• Four Alarm keypads will be upgrade with new Alpha 6160 Keypad throughout the district.	Information only
<ul style="list-style-type: none">• All four generators passed the annual inspection. One battery was replaced at the Beach generator. Inspection was performed by JSR Generator,	Information only
<ul style="list-style-type: none">• Total Work orders 1745, Open 55 as of 5/31/2024	Information only