

GLASSBORO PUBLIC SCHOOLS

DISTRICT PROJECT UPDATE

May 2026

District Wide Projects

High School

Description	Actions	Status
New roof leak	<ul style="list-style-type: none"> Band aid 	Work in progress
New LED light fixtures are being installed throughout the entire parking lot and in several classrooms	<ul style="list-style-type: none"> In House Parking lights and around the building has been updated to LED 	Work in progress
Boiler #2 Circulation pump leaking from packing	<ul style="list-style-type: none"> Maintenance team removed pump sent pump to be repacking (Seal) 	Completed
Classroom D28 Standalone HVAC Unit Malfunctioning	<ul style="list-style-type: none"> LGB Contractor Bad motor Bad transformer 	Completed
DEP of New Jersey Violation Year 2009	<ul style="list-style-type: none"> Architect FVHD 	Work in progress

Bowe

Description	Action	Status
	<ul style="list-style-type: none"> 	
Potholes	<ul style="list-style-type: none"> In house Monitoring until we have a permanently solution 	Work in progress
New Leak, Classrooms, hallaways, Gym, Art room	<ul style="list-style-type: none"> Summer Work (Referemdum) 	Work in progress
Upgrade of gas line that feeds gas meter outside boiler room	<ul style="list-style-type: none"> South Jersey Gas 5/16/2026 	Open

Bullock

Description	Actions	Status
School office ceiling unit making noise	<ul style="list-style-type: none"> Remove blower fan from unit , sent out to replaced bearings and shaft 	Completed
School Office roof leak	<ul style="list-style-type: none"> In house band aid 	Completed
Main entrance walk way two glass window broke do to snow fall from roof and broke the glasses	<ul style="list-style-type: none"> Remove one broken glass. Waiting to get an estimate 	Completed
Teacher lounge bad blower motor	<ul style="list-style-type: none"> Purchase anew motor Work done in-house 	Completed

Rodgers

Description	Actions	Status
Cafeteria Unit 1 needs new compressor	<ul style="list-style-type: none"> Waiting for quote 	Open
Cafeteria Unit 2 needs to be replaced	<ul style="list-style-type: none"> Waiting for quote 	Open
Boiler #2 Heat exchanger(vessel) is leaking	<ul style="list-style-type: none"> LGB Contractor Looking to see if it is still under warranty Looking into options 	Open
School Office copier room roof leak, Hallways	<ul style="list-style-type: none"> Summer Work (Referemdum) 	Work in progress
Cafeteria roof leak	<ul style="list-style-type: none"> Summer Work (Referemdum) 	Work in progress
Hallway outside Boiler room roof leak	<ul style="list-style-type: none"> Summer Work (Referemdum) 	Work in progress
Hallway outside cafeteria roof leak	<ul style="list-style-type: none"> Summer Work (Referemdum) 	Work in progress
Classroom D-4 Bad motor blower	<ul style="list-style-type: none"> Purchase anew motor Work done in-house 	Completed

Beach

Description	Action	Status
New Office for new Administrator	<ul style="list-style-type: none"> • Building a new office (Maintenance and Ground teams) • New door was ordered 	Work in progress

Ops/Transportation

Description	Action	Status
The access road requires repair due to an increasing number of potholes.	<p>Monitoring: I am scheduled to meet with Mr. Chip (Borough) to discuss the possibility of his assistance with interim remediation efforts.</p> <ul style="list-style-type: none"> • 	Completed

District Wide

Description	Status
<ul style="list-style-type: none"> • FD to GHS False alarm. 	Informational only
<ul style="list-style-type: none"> • The 2026 FD Annual Inspection of the entire School District has been completed, and the new Certificate of Inspection has been received. 	Informational only
<ul style="list-style-type: none"> • Total Work orders this month 20 as of 4/13/2026 	Information only

Referendum

USA Roofer	Came to Rodgers and Admin Building to visually inspect the roof and assests the roof composition of each building.	
FVHD and admin	Walked the gym to discuss options	